

Kronos V2.622.0000000.5.R.181215

Release Notes

ZHEJIANG DAHUA VISION TECHNOLOGY CO., LTD.

Legal Information

Copyright

© 2018 ZHEJIANG DAHUA VISION TECHNOLOGY CO., LTD. All rights reserved.

This document cannot be copied, transferred, distributed, or saved in any form without the prior written permission of Zhejiang Dahua Vision Technology Co., LTD (hereinafter referred to be "Dahua").

The products described in this document may contain the software that belongs to Dahua or the third party. Without the prior written approval of the corresponding party, any person cannot (including but not limited to) copy, distribute, amend, abstract, reverse compile, decode, reverse engineer, rent, transfer, sublicense the software.

Trademarks



All other company names and trademarks mentioned herein are the properties of their respective owners.

Disclaimer

- These release notes are for reference only, and the actual product shall prevail.
- Succeeding products and release notes are subject to change without notice.
- If there is any uncertainty or controversy, please refer to our final explanation.

Table of Contents

Legal Information	
Release Notes	
1.1 Overview	1
1.2 New Features	1
1.3 Fixed Bugs	1
1.4 Compatibility	1
1.4.1 Program	1
1.4.2 Browser	
1.4.3 Third Party Access	2
1.5 Software Environment	2
1.6 Pending Issues	2
1.7 Undate Guide	2

Release Notes

1.1 Overview

Item	Description
Product model	Kronos platform series
Version	V2.622.0000000.5.R.181215
Software package	DH_IPC-HX8X4X-Kronos_Eng_P_Stream3_V2.622.0000000.5.R.181215.zip
information	DH_IPC-HX8X4X-Kronos_EngSpnFrn_N_Stream3_V2.622.0000000.5.R.181215.zip
OS requirement	None
Release date	2018/12/25

1.2 New Features

Feature	Description	
1	Comply with security baseline V1.3, including GDPR.	
2	Support in-area people counting.	
3	Support in-area people counting report, including daily report and monthly report. You can view the corresponding passenger flow.	
4	Support loitering alarm for in-area people counting. The alarm will be triggered if the loitering duration or people quantity exceeds the defined value.	
5	You can click the "+" sign to add a new rule for people counting and in-area people counting.	

1.3 Fixed Bugs

Fixed bugs	Description
1	The in-area people counting accuracy did not reach the standard, especially when the
	installation height is 5 m.
2	When in-area people counting runs for a while, all the detection boxes on people's head
	would disappear and then appear.
3	The OSD overlay of people counting result is not aligned with the title.

1.4 Compatibility

1.4.1 Program

• For IPC-HX7XXX, IPC-HX8XXX, the programs are compatible with the previous release.

1.4.2 Browser

IE8\9\IE10\IE11\Firefox (Use Firefox under V48)

1.4.3 Third Party Access

CGI testing tool version: V3.01.0ONVIF testing tool version: V18.06

• ONVIF: Supports ProfileG

MILESTONE testing tool version: Xprotect Corporate 2018, device pack 9.6a

GENETEC testing tool version: Security Desk 5.7 GA

1.5 Software Environment

Platform	Model	Version	
	NVR5832-4KS2	Customer_NVR5XXX-4KS2_MultiLang_StereoNumber_DH_V3.216.00	
NVR		12000.0.T.20180917.zip	
Client	SmartPSS	DH_SMARTPSS-Win32_ChnEng_IS_V2.002.9995001.0.T.180918.zip	
EasyView /		1	
	Player	General_SmartPlayer-Win32_Chn_IS_V4.000.0000000.5.R.20180201.	
		zip	
ConfigTool General_ConfigTool_Cl		General_ConfigTool_ChnEng_V4.011.0000000.0.R.20180906.zip	
1001	PlaySDK	General_PlaySDK_Chn_Windows32_IS_V3.040.0000000.2.R.180704.	
		zip	
	NetSDK	General_NetSDK_Chn_Win32_IS_V3.050.0000004.0.R.181121	
DSS	/	1	

1.6 Pending Issues

No.	Issue description	Possible result	How to fix
1	When the camera	Unreported alarms.	None
	installation height is 5 m		Optimize the algorithm.
	and the lens is not		
	perpendicular to the		
	ground, the people		
	counting accuracy is		
	88%, but the standard is		
	90%.		
2	When the camera	Unreported alarms.	None
	installation height is 5 m		Optimize the algorithm.
	and the lens is		
	perpendicular to the		
	ground, the people		
	counting accuracy is		
	95.44%, but the standard		
	is 98%.		

No.	Issue description	Possible result	How to fix
3	The mainstream	The mainstream	Disable the second sub stream.
	resolution is fixed to be	resolution can not be	
	2048x1536 when the	changed when the	
	second sub stream is	second sub stream is	
	enabled.	enabled.	

1.7 Update Guide

None





ZHEJIANG DAHUA VISION TECHNOLOGY CO., LTD.

Address: No.1199, Bin'an Road, Binjiang District, Hangzhou, P.R. China

Postcode: 310053 Tel: +86-571-87688883

Fax: +86-571-87688815

Email: overseas@dahuatech.com Website: www.dahuasecurity.com