ITC215(237)-PW6M-XXX-C2 V2.626.0000000.4.R.220718

Release Notes

Foreword

Disclaimer

- These release notes are for reference only. Slight differences might be found between the release notes and the product.
- Succeeding products and release notes are subject to change without notice.
- If there is any uncertainty or controversy, we reserve the right of final explanation.

Trademarks

All the company names and trademarks mentioned herein are the properties of their respective owners.

Table of Contents

Release Notes

1.1 Overview

Item	Description
Product model	ITC215/237-PW6M-XXX-C2 ANPR Camera
Version	V2.626.0000000.4.R.220708
Software package information	General_ITC(X15)(X37)-PW6M-XXX-C2_Eng_PN_Oversea_V2.626.0000000.4.R.220708.zip
OS requirement	None
Release date	July 19, 2022

1.2 New Features

Fixed Bug	Description
1	Higher cyber security.

1.3 Fixed Bugs

None.

1.4 Compatibility

1.4.1 Program

- V2.626.0000000.3.R.220520
    - ◇ Supports initialization during first login after startup.
    - ◇ Supports multiple languages.
- V2.626.0000000.2.R.220402
    - ◇ When the country is set to a North American country, the algorithm did not take effect
    - ◇ When connected to a NVR, the camera might fail to display images.

When updating from V2.625, restore the configurations to get better user experience.

1.4.2 Browser

With plug-ins: IE9\IE10\IE11\Firefox (52 and earlier versions)\Chrome (42 and earlier versions)

Without plug-ins: Chrome (92 and later versions)

1.4.3 Third Party Access

ONVIF testing tool version: V20.12

1.5 Software Environment

Category	Model	Version
Tool	Player	General_SmartPlayer-Win32_Eng_IS_V4.000.0000001.4.R.191009.zip
	ConfigTool	General_ConfigTool_ChnEng_V4.011.0000003.7.R.20200325.zip
Platform	PMS	General_PMS_Eng_Basic_V1.003.0000001.0.R.20191126.zip

1.6 Update Guide

⚠️

- Updating with a wrong program might result in device failure.
- Ensure stable power supply and network connection, and that the camera is not restarted and the web page is not closed during update.

Step 1   Select **Setting** > **System Management** > **System Upgrade**.

Step 2   Import the updated file.

1) Click **Import** to import the update file. The file name is "2.6XX.0000000.X.R.YYMMDD.bin".

2) Click **Upgrade**. The update process takes 2 to 5 minutes (The actual update time differs among devices).