ITC215(237)-PW6M-XXX-C2 V5.000.0000000.0.R.230403

Release Notes

Foreword

Disclaimer

- These release notes are for reference only. Slight differences might be found between the release notes and the product.
- Succeeding products and release notes are subject to change without notice.
- If there is any uncertainty or controversy, we reserve the right of final explanation.

Trademarks

All the company names and trademarks mentioned herein are the properties of their respective owners.

Table of Contents

Release Notes

1.1 Overview

Item	Description
Product model	ITC215/237-PW6M-XXX-C2 ANPR Camera
Version	V5.000.0000000.0.R.230403
Software package information	General_ITC(X15)(X37)-PW6M-XXX-C2_MultiLang_PN_Oversea_V5.000.0000000.0.R.230403.zip
OS requirement	None
Release date	April 19, 2023

1.2 New Features

No.	Description
1	Brand-new web 5.0 design.
2	Brand-new **Live View** page.

1.3 Fixed Bugs

None.

1.4 Compatibility

1.4.1 Program

- V2.626.0000000.4.R.220718
  - ◇ Higher cyber security
- V2.626.0000000.3.R.220520
  - ◇ Supports initialization during first login after startup.
  - ◇ Supports multiple languages.
- V2.626.0000000.2.R.220402
  - ◇ When the country is set to a North American country, the algorithm did not take effect
  - ◇ When connected to a NVR, the camera might fail to display images.

📖

The program has to be updated to V2.626.0000000.4.R.220718 or V2.626.0000000.3.R.220520 before it can be updated to V5.000. Otherwise, the update might fail.

When updating from V2.625, restore the configurations for better user experience.

1.4.2 Browser

Chrome/Microsoft Edge

Plug-ins are not required for most functions. For certain functions that require plug-ins, open the webpage on Chrome or Microsoft Edge.

1.4.3 Third Party Access

ONVIF testing tool version: V20.12

1.5 Software Environment

Category	Model	Version
Tool	Player	General_SmartPlayer-Win32_Eng_IS_V4.000.0000001.4.R.191009.zip
	ConfigTool	General_ConfigTool_ChnEng_V4.011.0000003.7.R.20200325.zip

1.6 Update Guide

- Updating with a wrong program might result in device failure.
- Ensure stable power supply and network connection, and that the camera is not restarted and the web page is not closed during update.

Step 1   Select **Setting** > **System** > **Update**.

Step 2   Import the updated file.
1) Click **Import** to import the update file. The file name is "5.00X.0000000.X.R.YYMMDD.bin".
2) Click **Update**. The update process takes 2 to 5 minutes (The actual update time differs among devices).