



**LEO V2.800.0000000.39.R.220726**

**Release Notes**



# Legal Information

## Copyright

© 2022 ZHEJIANG DAHUA VISION TECHNOLOGY CO., LTD. All rights reserved.

This document cannot be copied, transferred, distributed, or saved in any form without the prior written permission of Zhejiang Dahua Vision Technology Co., LTD (hereinafter referred to as "Dahua").

The products described in this document may contain the software that belongs to Dahua or the third party. Without the prior written approval of the corresponding party, any person cannot (including but not limited to) copy, distribute, amend, abstract, reverse compile, decode, reverse engineer, rent, transfer, sublicense the software.

## Trademarks

 ,  ,  , and **HDCVI** are the trademarks or registered trademarks of Dahua.

All other company names and trademarks mentioned herein are the properties of their respective owners.

## Disclaimer

- These release notes are for reference only. Slight differences might be found between the release notes and the product.
- Succeeding products and release notes are subject to change without notice.
- If there is any uncertainty or controversy, we reserve the right of final explanation.

# Table of Contents

<b>Legal Information .....</b>	<b>I</b>
<b>Release Notes .....</b>	<b>1</b>
1.1 Overview .....	1
1.2 New Features.....	1
1.3 Fixed Bugs .....	2
1.4 Compatibility.....	2
1.4.1 Program .....	2
1.4.2 Browser.....	2
1.4.3 Third Party Access.....	2
1.5 Software Environment.....	2
1.6 Pending Issues.....	3
1.7 Update Guide .....	3

# Release Notes

## 1.1 Overview

Item	Description
Product model	Leo Platform Series 25/32/34/35; Economic Fisheye Camera
Version	V2.800.0000000.39.R.220726
Software package information	<ul style="list-style-type: none"> <li>● DH_IPC-HX3XXX-Leo_MultiLang_NP_Stream3_V2.800.0000000.39.R.220726.zip</li> <li>● DH_IPC-HX3XXX-Leo_MultiLang_PN_Stream3_V2.800.0000000.39.R.220726.zip</li> <li>● DH_IPC-HX5(4)(3)XXX-Leo_MultiLang_NP_Stream3_V2.800.0000000.39.R.220726.zip</li> <li>● DH_IPC-HX5(4)(3)XXX-Leo_MultiLang_PN_Stream3_V2.800.0000000.39.R.220726.zip</li> <li>● DH_IPC-HX5(4)(3)XXX-Leo_MultiLang_NP_Stream3-USA_V2.800.0000000.39.R.220726.zip</li> <li>● DH_IPC-EX5XXX-Leo_MultiLang_NP_Stream3_V2.800.0000000.39.R.220726.zip</li> <li>● DH_IPC-EX5XXX-Leo_MultiLang_PN_Stream3_V2.800.0000000.39.R.220726.zip</li> <li>● DH_IPC-EX5XXX-Leo_MultiLang_NP_Stream3-USA_V2.800.0000000.39.R.220726.zip</li> <li>● DH_IPC-HX2(5)XXX-Leo_MultiLang_PN_Stream2_V2.800.0000000.39.R.220726.zip</li> </ul>
OS requirement	None
Release date	July 31, 2022

## 1.2 New Features

Feature	Description	Recommendation
1	Enhanced product security.	★★★
2	Optimized strings of web client.	★★★

## 1.3 Fixed Bugs

Fixed Bug	Description
1	Updated face algorithm to solve problems related to the face sensitivity mapping.
2	Devices with AI Codec function cannot modify the configuration of stream frame rate.
3	Live view lags caused by overload metadata.
4	DMSS cannot receive the event after the sound and light device is disarmed with one click.
5	Modify the stream configuration, and then restart the device, but the modification does not take effect.
6	Failed to mount Dahua SD card with encryption function.

## 1.4 Compatibility

### 1.4.1 Program

It is compatible with the previous release.

### 1.4.2 Browser

IE: IE9, IE11

Firefox: 34.0.5.5443, 82.0.3

Chrome: 21.0.1180.11, 86.0.4240.198

### 1.4.3 Third Party Access

- ONVIF testing tool version: V20.06
- ONVIF: Supports ProfileG
- MILESTONE testing tool version: Milestone XProtect Corporate 2019 R2
- GENETEC testing tool version: Security Center Version 5.7SR1(5.7.529.12)

## 1.5 Software Environment

Platform	Model	Version
NVR	NVR4000-4K S2	2.6.02.02.00495 DH_NVR4XXX-4KS2_MultiLang_V4.001.0000003.1.R.200813.zip

	NVR5000-4KS2	2.6.01.02.08557 DH_NVR5XXX-4KS2_MultiLang_V4.001.0000003.1.R.200813.zip
	NVR4X-I	2.6.01.02.08571 DH_NVR4XXX-I_MultiLang_V4.001.0000000.2.R.200814.zip
	NVR5X-I	2.6.01.02.08563 DH_NVR5XXX-I_MultiLang_V4.001.0000000.2.R.200814.zip
EVS/IVS S	EVS5X	2.6.01.02.06170 DH_EVS50XX_Eng_V3.210.0000002.4.R.200220.bin
	EVS7X	2.6.01.02.07268 DH_EVS71XX_Eng_V4.001.0000000.2.R.200514.BIN
	IVSS7XX	2.6.01.02.07976 DH_IVSS7XX_Eng_V2.001.0000000.0.R.200703.BIN
APP	DMSS	General_DMSS-Android-Phone_MultiLang_Basic_IS_V1.000.0000002.2.R.200408
Tools	Player	2.8.02.01.00303 General_SmartPlayer-Win32_Eng_IS_V4.000.0000001.4.R.191009.zip
	ConfigTool	2.8.02.01.00407 General_ConfigTool_ChnEng_V4.011.0000003.7.R.20200325.zip
	SmartPSS	2.7.05.01.00850 DH_SMARTPSS-Win64_ChnEng_IS_V2.003.0000002.1.R.200602.Bugix.zip
DSS	Smart7016D-I	2.6.01.13.00156 General_SMARTDSS7XXX_Chn_Basic_V1.003.0000000.0.R.20200509.tar.gz
	C9100	2.4.01.01.12694 C9100_VideoCloud_V3.006_20200708.iso
	H8900	2.7.01.08.03904 General_DSS-H8900_Chn_Basic_V3.001.0000004.8.R.20200426.tar.gz
F7500	IVS-F7500-P-S2	2.7.07.01.00898 General_IVS-F7500-T-S2_ChnEng_DataNode-Base-MD5-0794_V1.002.0000002.5.R.200311.tar.gz

## 1.6 Pending Issues

None.

## 1.7 Update Guide

See the following points for the update:

- Do not disconnect the network, reboot and turn off the camera during update.
- When upgrading with the false file, you need to reboot the device, otherwise some functions might be disabled.

**ZHEJIANG DAHUA VISION TECHNOLOGY CO., LTD.**

Address: No.1199, Bin'an Road, Binjiang District, Hangzhou, P.R. China

Postcode: 310053

Tel: +86-571-87688883

Fax: +86-571-87688815

Email: [overseas@dahuatech.com](mailto:overseas@dahuatech.com)

Website: [www.dahuasecurity.com](http://www.dahuasecurity.com)