



LEO
V2.800.0000000.8.R.191231

Release Notes

ZHEJIANG DAHUA VISION TECHNOLOGY CO., LTD.

Copyright

© 2020 ZHEJIANG DAHUA VISION TECHNOLOGY CO., LTD. All rights reserved.

This document cannot be copied, transferred, distributed, or saved in any form without the prior written permission of Zhejiang Dahua Vision Technology Co., LTD (hereinafter referred to be "Dahua").

The products described in this document may contain the software that belongs to Dahua or the third party. Without the prior written approval of the corresponding party, any person cannot (including but not limited to) copy, distribute, amend, abstract, reverse compile, decode, reverse engineer, rent, transfer, sublicense the software.

Trademarks

 and **HDCVI** are the trademarks or registered trademarks of Dahua.

All other company names and trademarks mentioned herein are the properties of their respective owners.

Disclaimer

- These release notes are for reference only, and the actual product shall prevail.
- Succeeding products and release notes are subject to change without notice.
- If there is any uncertainty or controversy, please refer to our final explanation.



Table of Contents

Legal Information	I
Release Notes	1
1.1 Overview	1
1.2 New Features	1
1.3 Fixed Bugs	1
1.4 Compatibility	1
1.4.1 Program	1
1.4.2 Browser	1
1.4.3 Third Party Access	1
1.5 Software Environment	2
1.6 Pending Issues	2
1.7 Update Guide	2

1.1 Overview

Item	Description
Product model	LEO platform overseas 3 series product
Version	V2.800.0000000.8.R.191231
Software package information	DH_IPC-HX5(4)(3)XXX-Leo_MultiLang_PN_Stream3_V2.800.0000000.8.R.191231.zip DH_IPC-HX5(4)(3)XXX-Leo_MultiLang_NP_Stream3_V2.800.0000000.8.R.191231.zip DH_IPC-HX3XXX-Leo_MultiLang_PN_Stream3_V2.800.0000000.8.R.191231.zip DH_IPC-HX3XXX-Leo_MultiLang_NP_Stream3_V2.800.0000000.8.R.191231.zip
OS requirement	None
Release date	2020/1/13

1.2 New Features

Features	Description
1	Supports the models with full-color 3.6mm lens.
2	The camera will automatically restart after SD card is formatted.

1.3 Fixed Bugs

Fixed Bugs	Description
1	The screen will blur when the camera acquires a sub stream through CGI.
2	The audio might be abnormal when the audio component runs for a long time.

1.4 Compatibility

1.4.1 Program

It is compatible with the previous release.

1.4.2 Browser

IE: IE9、IE11

Firefox: 34.0.5.5443、50.1.0.6186

Chrome: 21.0.1180.11、51.0.2704.103

1.4.3 Third Party Access

- CGI testing tool version: V3.01.6
- ONVIF testing tool version: V18.12

- ONVIF: Supports ProfileG
- MILESTONE testing tool version: Milestone XProtect Corporate 2019 R2
- GENETEC testing tool version: Security Center Version 5.7SR1(5.7.529.12)

1.5 Software Environment

Platform	Model	Version
NVR	NVR4000-4KS2	2.6.01.02.04048 DH_NVR4XXX-4KS2_MultiLang_V4.000.0000001.1.R.190830.zip
	NVR5000-4KS2	2.6.01.02.03713 DH_NVR5XXX-4KS2_MultiLang_NP_V4.000.0000000.1.R.20190809.zip
Client	DMSS	V4.70.0000
Tools	Player	2.1.02.01.18297: General_SmartPlayer-Win32_Eng_IS_V4.000.0000000.5.R.20180201.zip
	ConfigTool	2.8.03.01.00070: General_ConfigTool_ChnEng_V4.011.0000003.5.R.20190722.zip
DSS	DSS pro DSS express	DSS-PRO: 2.7.01.02.00376:General_DSS-PRO_Win64_IS_V7.002.000000 2.1.R.20190418.exe DSS-EXPERSS: 2.7.01.02.00599:General_DSS-Express_win32_IS_V1.000.000 0003.1.R.20190817.exe

1.6 Pending Issues

None.

1.7 Update Guide

See the following points for the update:

1. Do not disconnect the network, reboot and turn off the camera during update.
2. When upgrading with the false file, you need to reboot the device, otherwise some functions might be disabled.

ZHEJIANG DAHUA VISION TECHNOLOGY CO., LTD.

Address: No.1199, Bin'an Road, Binjiang District, Hangzhou, P.R. China

Postcode: 310053

Tel: +86-571-87688883

Fax: +86-571-87688815

Email: overseas@dahuatech.com

Website: www.dahuasecurity.com