



LEO
V2.800.0000000.9.R.200324

Release Notes

ZHEJIANG DAHUA VISION TECHNOLOGY CO., LTD.

Copyright

© 2020 ZHEJIANG DAHUA VISION TECHNOLOGY CO., LTD. All rights reserved.

This document cannot be copied, transferred, distributed, or saved in any form without the prior written permission of Zhejiang Dahua Vision Technology Co., LTD (hereinafter referred to be "Dahua").

The products described in this document may contain the software that belongs to Dahua or the third party. Without the prior written approval of the corresponding party, any person cannot (including but not limited to) copy, distribute, amend, abstract, reverse compile, decode, reverse engineer, rent, transfer, sublicense the software.

Trademarks

 and **HDCVI** are the trademarks or registered trademarks of Dahua.

All other company names and trademarks mentioned herein are the properties of their respective owners.

Disclaimer

- These release notes are for reference only, and the actual product shall prevail.
- Succeeding products and release notes are subject to change without notice.
- If there is any uncertainty or controversy, please refer to our final explanation.



Table of Contents

Legal Information	I
Release Notes	1
1.1 Overview	1
1.2 New Features	1
1.3 Fixed Bugs	1
1.4 Compatibility.....	1
1.4.1 Program	1
1.4.2 Browser.....	1
1.4.3 Third Party Access.....	1
1.5 Software Environment.....	2
1.6 Pending Issues.....	2
1.7 Update Guide.....	3

1.1 Overview

Item	Description
Product model	LEO platform overseas 3 series product
Version	V2.800.0000000.9.R.200324
Software package information	DH_IPC-HX5(4)(3)XXX-Leo_MultiLang_PN_Stream3_V2.800.0000000.9.R.200324.zip DH_IPC-HX5(4)(3)XXX-Leo_MultiLang_NP_Stream3_V2.800.0000000.9.R.200324.zip DH_IPC-HX3XXX-Leo_MultiLang_NP_Stream3_V2.800.0000000.9.R.200324.zip DH_IPC-HX3XXX-Leo_MultiLang_PN_Stream3_V2.800.0000000.9.R.200324.zip
OS requirement	None
Release date	2020/4/15

1.2 New Features

Features	Description
1	Supports full-color 5MP cameras.
2	Supports Register function.

1.3 Fixed Bugs

Fixed Bugs	Description
1	The audio will be abnormal when the audio noise filtering algorithm runs for a long time.

1.4 Compatibility

1.4.1 Program

It is compatible with the previous release.

1.4.2 Browser

IE: IE9、IE11

Firefox: 34.0.5.5443、50.1.0.6186

Chrome: 21.0.1180.11、51.0.2704.103

1.4.3 Third Party Access

- CGI testing tool version: V3.01.6
- ONVIF testing tool version: V19.12

- ONVIF: Supports ProfileG
- MILESTONE testing tool version: Milestone XProtect Corporate 2019 R2
- GENETEC testing tool version: Security Center Version 5.7SR1(5.7.529.12)

1.5 Software Environment

Platform	Model	Version
NVR	NVR4000-4KS2	2.6.01.02.05173 DH_NVR4XXX-4KS2_MultiLang_V4.000.0000001.4.R.191129.zip 2.6.01.02.05171 DH_NVR4XXX-4KS2_Chn_V4.000.0000001.4.R.191129.zip 2.6.01.02.05168 DH_NVR4XXX-4KS2L_MultiLang_V4.000.0000001.0.R.191129.zip
	NVR5000-4KS2	2.6.01.02.05178 DH_NVR5XXX-4KS2_MultiLang_V4.000.0000001.3.R.20191129.zip 2.6.01.02.05176 DH_NVR5XXX-4KS2_Chn_V4.000.0000001.3.R.20191129.zip
	NVR5X-I	2.6.01.02.03719 DH_NVR5XXX-I_Chn_P_V4.000.0000000.1.R.20190809.zip 2.6.01.02.03721 DH_NVR5XXX-I_MultiLang_NP_V4.000.0000000.1.R.20190809.zip
EVS/IVS S	EVS5X	2.6.01.02.02938 DH_EVS50XX_Chn_V3.210.0000002.3.R.190603.bin 2.6.01.02.02943 DH_EVS50XX_Eng_V3.210.0000002.3.R.190603.bin
	EVS7X	2.6.01.02.02947、2.6.01.02.02949 DH_EVS70XX_Chn_V3.210.0000002.3.R.190603.bin General_EVS70XX_Chn_V3.210.0000002.3.R.190603.bin
	IVSS7XX	2.6.01.02.05455 DH_IVSS7XX_Chn_V2.000.0000002.0.R.191206.BIN 2.6.01.02.05457 DH_IVSS7XX_Eng_V2.000.0000002.0.R.191206.BIN 2.6.01.02.05459 General_IVSS7XX_Chn_V2.000.0000002.0.R.191206.BIN 2.6.01.02.05461 General_IVSS7XX_Eng_V2.000.0000002.0.R.191206.BIN 2.6.01.02.05463 DH_IVSS_Chn_PXE_V2.000.0000002.0.R.191206.zip 2.6.01.02.05465 DH_IVSS_Eng_PXE_V2.000.0000002.0.R.191206.zip 2.6.01.02.05467 General_IVSS_Chn_PXE_V2.000.0000002.0.R.191206.zip 2.6.01.02.05469 General_IVSS_Eng_PXE_V2.000.0000002.0.R.191206.zip
APP	IMou	V3.15.8
Tools	Player	2.8.02.01.00302 General_SmartPlayer-Win32_Chn_IS_V4.000.0000001.4.R.191009.zip 2.8.02.01.00303 General_SmartPlayer-Win32_Eng_IS_V4.000.0000001.4.R.191009.zip
	ConfigTool	2.8.03.01.00070: General_ConfigTool_ChnEng_V4.011.0000003.5.R.20190722.zip

	SmartPSS	2.7.05.01.00551: DH_SMARTPSS-Win64_ChnEng_IS_V2.003.0000001.0.R.191028.zip
DSS	Smart7016D-I	2.6.01.13.00134 General_SMARTDSS7XXX_Chn_Basic_V1.002.0000002.1.R.20191220.tar.gz
	C9100	2.7.01.01.00482 General_DSSC9100_MultiLang_V3.000.0000009.3.R.190927.tar.gz
	H8900	2.7.01.08.02075 General_DSS-H8900_Chn_Basic_V3.001.0000003.9.R.20190918.tar.gz
F7500	IVS-F7500-P-S2	2.7.07.01.00269 General_IVS-F7500-P-S2_ChnEng_Base_V1.002.9995001.0.R.190603.tar.gz

1.6 Pending Issues

None.

1.7 Update Guide

See the following points for the update:

1. Do not disconnect the network, reboot and turn off the camera during update.
2. When upgrading with the false file, you need to reboot the device, otherwise some functions might be disabled.

ZHEJIANG DAHUA VISION TECHNOLOGY CO., LTD.

Address: No.1199, Bin'an Road, Binjiang District, Hangzhou, P.R. China

Postcode: 310053

Tel: +86-571-87688883

Fax: +86-571-87688815

Email: overseas@dahuatech.com

Website: www.dahuasecurity.com