



Themis
V2.620.0000004.0.R.191130

Release Notes

Copyright

© 2019 ZHEJIANG DAHUA VISION TECHNOLOGY CO., LTD. All rights reserved.

This document cannot be copied, transferred, distributed, or saved in any form without the prior written permission of Zhejiang Dahua Vision Technology Co., LTD (hereinafter referred to be "Dahua").

The products described in this document may contain the software that belongs to Dahua or the third party. Without the prior written approval of the corresponding party, any person cannot (including but not limited to) copy, distribute, amend, abstract, reverse compile, decode, reverse engineer, rent, transfer, sublicense the software.

Trademarks

 and **HDCVI** are the trademarks or registered trademarks of Dahua.

All other company names and trademarks mentioned herein are the properties of their respective owners.

Disclaimer

- These release notes are for reference only, and the actual product shall prevail.
- Succeeding products and release notes are subject to change without notice.
- If there is any uncertainty or controversy, please refer to our final explanation.



Table of Contents

| | |
|--------------------------------|----------|
| Legal Information | I |
| Release Notes | 1 |
| 1.1 Overview | 1 |
| 1.2 New Features | 1 |
| 1.3 Fixed Bugs | 1 |
| 1.4 Compatibility | 1 |
| 1.4.1 Program | 1 |
| 1.4.2 Browser | 1 |
| 1.4.3 Third Party Access | 1 |
| 1.5 Software Environment | 2 |
| 1.6 Pending Issues | 2 |
| 1.7 Update Guide | 2 |

1.1 Overview

| Item | Description |
|------------------------------|---|
| Product model | Themis platform series |
| Version | V2.620.0000004.0.R.191130 |
| Software package information | DH_IPC-HX1X2X-Themis_Eng_P_V2.620.0000004.0.R.191130.zip DH_IPC-HX1X2X-Themis_EngSpn_N_V2.620.0000004.0.R.191130.zip DH_IPC-HX4X2X-Themis_Eng_P_Stream3_V2.620.0000004.0.R.191130.zip DH_IPC-HX4X2X-Themis_EngSpn_N_Stream3_V2.620.0000004.0.R.191130.zip DH_IPC-HX4X2X-Themis_Eng_P_Stream3_Wifi_V2.620.0000004.0.R.191130.zip DH_IPC-HX4X2X-Themis_EngSpn_N_Stream3_Wifi_V2.620.0000004.0.R.191130.zip p DH_IPC-HX5X2X-Themis_Eng_P_Stream3_V2.620.0000004.0.R.191130.zip DH_IPC-HX5X2X-Themis_EngSpn_N_Stream3_V2.620.0000004.0.R.191130.zip |
| OS requirement | None |
| Release date | 2019/12/9 |

1.2 New Features

None

1.3 Fixed Bugs

The camera cannot connect to the server through P2P.

1.4 Compatibility

1.4.1 Program

The programs are compatible with the previous release.

1.4.2 Browser

IE: IE9、IE11

1.4.3 Third Party Access

- CGI testing tool version: V2.0.0
- ONVIF testing tool version: V17.01
- ONVIF: Supports ProfileG
- GENETEC testing tool version: Security Center Version 1.83SR1

1.5 Software Environment

| Platform | Model | Version |
|----------|------------|--|
| NVR | NVR5208-4K | DH_NVR5XXX-4K_Eng_V3.215.0000000.0.R.20170814.zip |
| Client | SmartPSS | DH_SmartPSS_ChnEng_IS_V2.00.2.R.20170525.zip |
| | DMSS | <ul style="list-style-type: none"> ● iOS: V3.49.001 ● Android: V3.49.002 |
| Tool | Player | General_Player_Eng_WIN64_V3.44.0.R.170516.zip |
| | ConfigTool | General_ConfigTool_ChnEng_V4.08.0.R.20170727.zip |
| | PlaySDK | General_PlaySDK_Eng_Windows32_IS_V3.39.0.R.161102.zip |

1.6 Pending Issues

| No. | Issue description | Possible result | How to fix |
|-----|--|---|------------|
| 1 | When adding a user, enter a strong password that contains illegal characters, no illegal characters alarm when Click on the blank space. | This problem occurs only if the password contains illegal characters. | - |
| 2 | At 1.3Mp, click refresh button without prompt. | The encoding parameters such as resolution can be obtained normally, but no notice. | - |

1.7 Update Guide

None

ZHEJIANG DAHUA VISION TECHNOLOGY CO., LTD.

Address: No.1199, Bin'an Road, Binjiang District, Hangzhou, P.R. China

Postcode: 310053

Tel: +86-571-87688883

Fax: +86-571-87688815

Email: overseas@dahuatech.com

Website: www.dahuasecurity.com