



Edison
V2.680.0000000.15.R.200521
Release Notes

ZHEJIANG DAHUA VISION TECHNOLOGY CO., LTD.

Legal Information

Copyright

© 2019 ZHEJIANG DAHUA VISION TECHNOLOGY CO., LTD. All rights reserved.

This document cannot be copied, transferred, distributed, or saved in any form without the prior written permission of Zhejiang Dahua Vision Technology Co., LTD (hereinafter referred to be "Dahua").

The products described in this document may contain the software that belongs to Dahua or the third party. Without the prior written approval of the corresponding party, any person cannot (including but not limited to) copy, distribute, amend, abstract, reverse compile, decode, reverse engineer, rent, transfer, sublicense the software.

Trademarks

 and **HDCVI** are the trademarks or registered trademarks of Dahua.

All other company names and trademarks mentioned herein are the properties of their respective owners.

Disclaimer

- This release notes is for reference only, and the actual product shall prevail.
- Succeeding products and release notes are subject to change without notice.
- If there is any uncertainty or controversy, please refer to our final explanation.

Table of Contents

Legal Information	I
Release Notes	1
1.1 Overview	1
1.2 New Features	1
1.3 Fixed Bugs	1
1.4 Compatibility.....	1
1.4.1 Program	1
1.4.2 Browser.....	1
1.4.3 Third Party Access.....	1
1.5 Software Environment.....	2
1.6 Pending Issues.....	2
1.7 Upgrade Guide.....	2

Release Notes

1.1 Overview

Item	Description
Product model	Edison platform series
Version	V2.680.0000000.15.R.200521
Software package information	DH_IPC-HX13XX-Edison_EngSpnFrn_P_V2.680.0000000.15.R.200521.zip DH_IPC-HX13XX-Edison_EngSpnFrn_N_V2.680.0000000.15.R.200521.zip DH_IPC-HX2(1)XXX-Edison_EngSpnFrn_N_V2.680.0000000.15.R.200521.zip DH_IPC-HX2(1)XXX-Edison_EngSpnFrn_P_V2.680.0000000.15.R.200521.zip
OS requirement	None
Release date	2020/6/4

1.2 New Features

Feature	Description
1	None.

1.3 Fixed Bugs

Fixed bugs	Description
1、	None.

1.4 Compatibility

1.4.1 Program

- For 1230-S4(-QH) fixed focal series; 1230-ZS-S4 (-QH) vari-focal series
IPC-HX2(1)XXX-Edison
- For 1330-S4 fixed focal series
IPC-HX13XX-Edison

1.4.2 Browser

IE9\IE10\IE11\Firefox (You will be requested to install a plug-in when using the versions earlier than V52; otherwise, you can view the video without a plug-in.) \Chrome (You will be requested to install a plug-in when using the versions earlier than V42; otherwise, you can view the video without a plug-in.)

1.4.3 Third Party Access

- CGI: CGITestTool Version V1.001.0000001.0

- ONVIF testing tool version: V19.06
- ONVIF: Supports ProfileS

1.5 Software Environment

Platform	Model	Version
NVR	NVR2104HS-P-4KS2	DH_NVR2XXX-4KS2_MultiLang_V4.000.0000001.5.R.191218.zip
	NVR4232-4KS2	DH_NVR4XXX-4KS2_MultiLang_V4.001.0000000.0.R.200221.zip
Client	SmartPSS	DH_SMARTPSS-Win64_ChnEng_IS_V2.003.0000001.0.R.191028.zip
APP	DMSS	iDMSS Plus: 4.91.003 gDMSS Plus: 4.91.000
Tool	SmartPlayer	General_SmartPlayer-Win32_Eng_IS_V4.000.0000000.5.R.20180201.zip
	Configtool	General_ConfigTool_ChnEng_V4.011.0000003.5.R.20190722.zip
	DSS pro	General_DSS-PRO_Win64_IS_V7.002.0000003.0.R.20191008.exe
	DSS express	General_DSS-Express_win32_IS_V1.000.0000003.4.R.20190918.exe

1.6 Pending Issues

No.	Issue description	Possible result	How to fix
1	The system cannot recognize the SD card in exFAT format, and you can use it after formatting it.	You cannot use the SD card in exFAT format before formatting it.	Format the SD card first.
2	Change the log upper limit from 1024 to 512.	You can see less logs.	—

1.7 Upgrade Guide

None

ZHEJIANG DAHUA VISION TECHNOLOGY CO., LTD.

Address: No.1199, Bin'an Road, Binjiang District, Hangzhou, P.R. China

Postcode: 310053

Tel: +86-571-87688883

Fax: +86-571-87688815

Email: overseas@dahuatech.com

Website: www.dahuasecurity.com