

Prometheus V2.810.0000025.0.R210317

Release Notes





Legal Information

Copyright

© 2021 ZHEJIANG DAHUA VISION TECHNOLOGY CO., LTD. All rights reserved.

This document cannot be copied, transferred, distributed, or saved in any form without the prior written permission of Zhejiang Dahua Vision Technology Co., LTD (hereinafter referred to as "Dahua").

The products described in this document may contain the software that belongs to Dahua or the third party. Without the prior written approval of the corresponding party, any person cannot (including but not limited to) copy, distribute, amend, abstract, reverse compile, decode, reverse engineer, rent, transfer, sublicense the software.

Trademarks

alhua, **alhua**, and **HDCVI** are the trademarks or registered trademarks of Dahua.

All other company names and trademarks mentioned herein are the properties of their respective owners.

Disclaimer

- These release notes are for reference only, and the actual product shall prevail.
- Succeeding products and release notes are subject to change without notice.
- If there is any uncertainty or controversy, please refer to our final explanation.



Table of Contents

Legai Information	
Release Notes	
1.1 Overview	
1.2 New Features	
1.3 Fixed Bugs	
1.4 Compatibility	
1.4.1 Program	
1.4.2 Browser	
1.4.3 Third Party Access	
1.5 Software Environment	
1.6 Pending Issues	
1.7 Upgrade Guide	



Release Notes

1.1 Overview

Item	Description	
Product model	Prometheus platform series	
Version	V2.810.0000025.0.R.210317	
Software	DH_SD-Prometheus_MultiLang_NP_Stream3_V2.810.0000025.0.R.210317.zip	
package		
information	DH_SD-Prometheus_MultiLang_PN_Stream3_V2.810.0000025.0.R.210317.zip	
OS requirement	None	
Release date	April 1, 2021	

1.2 New Features

	Feature	Description	
1 Unified privacy masking function for cameras		Unified privacy masking function for cameras	
2 Displayed PCM on audio coding interface		Displayed PCM on audio coding interface	

1.3 Fixed Bugs

	Fixed Bugs	Description	
1 Default configuration of 4G module is not displayed			
Ī	2	Avigilon platform (ACC) connection failure	

1.4 Compatibility

1.4.1 Program

None.

1.4.2 Browser

IE9\IE10\IE11\Firefox\Chrome (Use Chrome under V42, and Firefox under V52). Google Chrome later than 42, Firefox later than 52, and Win10-edge.



1.4.3 Third Party Access

CGI testing tool version: V3.01.6.RONVIF testing tool version: V19.06

ONVIF: Supports Profile G

• MILESTONE testing tool version: Xprotect Corporate 2019 R1, device pack 10.2a

GENETEC testing tool version: Security Desk 5.7R4

1.5 Software Environment

Category	Model	Version	
	NVR5864-I	DH_NVR5XXX-I_Chn_V3.215.0000011.0.R.20190130.zip	
NVR	DHI-NVR4832-I	DH_NVR5XXX-I_MultiLang_V3.215.0000011.0.R.2019013	
	DHI-NVN4032-I	0.zip	
	SmartPSS	DH_SMARTPSS-Win32_ChnEng_IS_V2.002.0000007.0.R.1	
	Siliartess	81023.zip	
Client	lient DMSS	DMSS Plus 4.31.000	
	ConfigTool	DH_ConfigTool_ChnEng_V4.011.0000000.0.R.20180906.	
		zip	
	NKB1000	DH_NKB1000_ChnEng_V2.620.0000000.0.R.20180115.zi	
NKB	TAKETOOO	р	
NKB5000	DH_NKB5000_All_V3.211.10SA000.1.R.181204.BIN		
	Video cloud baseline	DH_DSSC9100_Internal_V3.000.0000006.9.R.190113.tar.	
Platform	C9100	gz	
FIGUOTIII	DSS Pro	DH_DSS-PRO_Win64_IS_V7.002.0000002.0.R.20190329.e	
	D33 FIO	xe	

1.6 Pending Issues

No.	Issue Description	Possible Results	How to Fix
1	When multiple faces are detected, some faces might not be captured through ftp.	Has some effect in the case of large amount of data because there might be data loss.	Use SD card instead of FTP to avoid image loss due to the nature of FTP.
2	After drawing face detection area and clicking Save, the detection box disappears.	Has no effect.	Clear the configuration when the product is delivered out of factory.



No.	Issue Description	Possible Results	How to Fix
	When multiple faces are		Do not enable email
3	detected, not all linked	Has little effect.	linkage when using the
	emails are received.		function.
	When playing live video		
	through RTMP, and using		
	domain c-2_f.dahuatech.com		When playing live
4	with the IP address of	Has little effect.	video through RTMP,
	10.172.179.243, the server		do not use this domain.
	cannot acquire stream and		
	keeps loading.		

1.7 Upgrade Guide

Refer to *ConfigTool Instructions*. Try to keep the power on during upgrading even though this platform enables dual back up. If the release date of the program is earlier than June 1,2019 upgrade the following program first: 2.6.01.05.09525

DH_SD-Prometheus_Chn_PN_Stream3_V2.800.0000000.7.R.190607.zip. Then upgrade to the latest program.

ZHEJIANG DAHUA VISION TECHNOLOGY CO., LTD.

Address: No.1199, Bin'an Road, Binjiang District, Hangzhou, P.R. China

Postcode: 310053 Tel: +86-571-87688883 Fax: +86-571-87688815

Email: overseas@dahuatech.com Website: www.dahuasecurity.com