

Hertz2_V2.800.0000000.17.R.230 706

Release Notes



ZHEJIANG DAHUA VISION TECHNOLOGY CO., LTD.



Legal Information

Copyright

© 2023 ZHEJIANG DAHUA VISION TECHNOLOGY CO., LTD. All rights reserved.

This document cannot be copied, transferred, distributed, or saved in any form without the prior written permission of Zhejiang Dahua Vision Technology Co., LTD (hereinafter referred to as "Dahua").

The products described in this document may contain the software that belongs to Dahua or the third-party. Without the prior written approval of the relevant owner, any person cannot (including but not limited to) copy, distribute, amend, abstract, reverse compile, decode, reverse engineer, rent, transfer, sublicense the software.

Trademarks

alhua, **alhua**, **alhua**, and **HDCVI** are the trademarks or registered trademarks of Dahua.

All other company names and trademarks mentioned herein are the properties of their respective owners.

Disclaimer

- This document is provided **as-is**. Unless applicable law requires, nothing herein should be constructed as constituting any express or implied warranty.
- Information and views expressed in this document might change without prior notice.
- If there is any uncertainty or controversy, we reserve the right of final explanation.



Table of Contents

| Legai i | ntormation | •• |
|---------|--------------------------|-----|
| 1 Relea | ase Note | . 1 |
| | Overview | |
| 1.2 | New Features | 1 |
| 1.3 | Fixed Bugs | 1 |
| 1.4 | Compatibility | 2 |
| | 1.4.1 Program | |
| | 1.4.2 Browser | |
| | 1.4.3 Third-party Access | . 2 |
| 1.5 | Software Environment | 2 |
| 1.6 | Pending Issues | 3 |
| 1.7 | Update Guide | 3 |



1 Release Note

1.1 Overview

| Product name | duct name Minimal Wi–Fi bullet & eyeball camera series | |
|------------------|--|--|
| Version | V2.800.0000000.17.R.230706 | |
| | DH_IPC-WX-Web-Hertz2_EngSpnRus_NP_V2.800.0000000.17.R. 230706.zip | |
| Software package | DH_IPC-WX-Web-Hertz2_EngSpnRus_PN_V2.800.0000000.17.R. 230706.zip | |
| information | DH_IPC-HX1(2)4XX-Hertz2_EngSpnRus_NP_V2.800.0000000.17.R. 230706.zip | |
| | DH_IPC-HX1(2)4XX-Hertz2_EngSpnRus_PN_V2.800.0000000.17.R. 230706.zip | |
| OS requirement | None | |
| Release date | July 6, 2023 | |

1.2 New Features

For IPC-WX-Web-Hertz2 series:

| No. | Feature Description |
|-----|---|
| 1 | Add RTC timing chip. Compatible with motherboards that support RTC. |

For IPC-HX1(2)4XX-Hertz2 series:

| No. | Feature Description |
|-----|--|
| 1 | Add 1 line for geographic location and 1 line for OSD customization. Supports 1+4 lines. |
| 2 | New sensor 2331 is used. |

1.3 Fixed Bugs

| No. | Bug Description | |
|-----|---|--|
| 1 | Fixed the issue that when motion detection and human detection were both enabled, after the configuration was changed to only report human detection events, but not report motion detection events, the NVR could not receive SMD events and could not link video recording. | |
| 2 | Fixed the issue that when the device was used alone, the device time could not be automatically synced after it restarted, which resulted in the videos saving under the calendar of the year 2000 because the hardware does not support RTC chips. | |
| 3 | After the device was added to NVR in cascade mode and NVR was added to the app, no SMD event messages were received in the app. | |



| No. | Bug Description |
|-----|--|
| 4 | The NVR had a black screen problem occasionally after the device was added to NVR for few days. |
| 5 | Time sync could not be performed to the device on NVR after the device was added to a new NVR by IP. |
| 6 | The device could not be added to the app after the port 10000 was disabled. |
| 7 | Fixed the issue that the device could be added to Imou App after the access library was updated. |

1.4 Compatibility

1.4.1 Program

This is a revision version, which is compatible with earlier versions.

1.4.2 Browser

IE 11; Chrome 111

1.4.3 Third-party Access

CGI testing tool version: V2.91.03
ONVIF testing tool version: V21.12

3. DMSS app: 1.99.430 2023.06.08

1.5 Software Environment

| Category | Model | Version |
|----------|-------------------|---|
| | NVR1108HS-8P-S3/H | DH_NVR1XXX- S3H_MultiLang_V4.001.000000 7.3.R.220315.zip |
| NVR | NVR2216-4KS2 | DH_NVR2XXX-4KS2_MultiLang _V4.001.0000005.0.R. 210709.zip |
| | NVR2104-S3 | DH_NVR2XXX- S3_MultiLang_V4.000.0000000. 0.R.211126.zip |
| | NVR4208-4KS2/L | DH_NVR4x-4KS2L_MultiLang_V 4.002.00000000.2.R.220121.zip |
| Client | DMSS APP | 1.99.430 2023.06.08 |



| Category | Model | Version |
|------------|-------------|---|
| Tool | ConfigTool | General_ConfigTool_ChnEng_ V5.000.0000001.8.R. 20210625.zip |
| Platform | DSS Pro | V8.0.4 |
| Fiationiii | DSS Express | V8.0.4 |

1.6 Pending Issues

None.

1.7 Update Guide

- 1. Update on web page: If there is no special requirement, see Web operation manual for update procedures.
- 2. Remote update by app:
 - a. Select **Cloud Upgrade**, and then check whether there is a new version available. If there is, click to update.
 - b. Do not disconnect the network, reboot or turn off the camera during update.
 - c. When updating with the false file, you need to reboot the device, otherwise some functions might be disabled.

