



Hertz V2.840.0000000.6.R.230111

Release Notes



Legal Information

Copyright

© 2023 ZHEJIANG DAHUA VISION TECHNOLOGY CO., LTD. All rights reserved.

This document cannot be copied, transferred, distributed, or saved in any form without the prior written permission of Zhejiang Dahua Vision Technology Co., LTD (hereinafter referred to as "Dahua").

The products described in this document may contain the software that belongs to Dahua or the third party. Without the prior written approval of the corresponding party, any person cannot (including but not limited to) copy, distribute, amend, abstract, reverse compile, decode, reverse engineer, rent, transfer, sublicense the software.

Trademarks

The image shows three variations of the Dahua logo: a stylized lowercase "dahua" with a red accent, a lowercase "dahua" with a red accent and "TECHNOLOGY" below it, and a lowercase "dahua" with "TECHNOLOGY" below it. These are followed by the text "and HDCVI" and "are the trademarks or registered trademarks of Dahua."

All other company names and trademarks mentioned herein are the properties of their respective owners.

Disclaimer

- These release notes are for reference only, and the actual product shall prevail.
- Succeeding products and release notes are subject to change without notice.
- If there is any uncertainty or controversy, please refer to our final explanation.

Table of Contents

Legal Information	I
Release Notes	1
1.1 Overview	1
1.2 New Features.....	1
1.3 Fixed Bugs	1
1.4 Compatibility.....	1
1.4.1 Program	1
1.4.2 Browser	1
1.4.3 Third Party Access	1
1.5 Software Environment.....	2
1.6 Pending Issues.....	2
1.7 Update Guide	2

Release Notes

1.1 Overview

Item	Description
Product model	Hertz platform series
Version	V2.840.0000000.6.R.230111
Software package information	DH_IPC-HX18XX-Molec_EngSpnRus_PN_V2.840.0000000.6.R.230111.zip DH_IPC-HX1XXX-Hertz2_EngSpnRus_PN_V2.840.0000000.6.R.230111.zip DH_IPC-HX1XXX-Hertz_EngSpnRus_PN_V2.840.0000000.6.R.230111.zip DH_IPC-HX2(1)XXX-Euler_EngSpnRus_NP_V2.840.0000000.6.R.230111.zip DH_IPC-HX2(1)XXX-Euler_EngSpnRus_PN_V2.840.0000000.6.R.230111.zip DH_IPC-HX2(1)XXX-Molec_EngSpnRus_NP_V2.840.0000000.6.R.230111.zip DH_IPC-HX2(1)XXX-Molec_EngSpnRus_PN_V2.840.0000000.6.R.230111.zip
OS requirement	None
Release date	February 10, 2023

1.2 New Features

Feature	Description
1	For automatic registration, you can enter the domain name instead of the IP address of the server.

1.3 Fixed Bugs

Fixed bugs	Description
1	None

1.4 Compatibility

1.4.1 Program

Compatible with earlier versions.

1.4.2 Browser

IE9\IE10\IE11\Firefox\Chrome (Use Chrome under V42, and Firefox under V52)

1.4.3 Third Party Access

- CGI testing tool version: V2.91.1.1
- ONVIF testing tool version: V21.12
- ONVIF: Supports ProfileS, T

1.5 Software Environment

Category	Model	Version
NVR	NVR2216-4KS2	DH_NVR2XXX-4KS2_MultiLang_V4.001.0000005.0.R.210709.zip
	NVR4216-16P-4KS2/L	DH_NVR4x-4KS2L_MultiLang_V4.002.0000000.3.R.220322.zip
	NVR2104-P-S3	DH_NVR2XXX-S3_MultiLang_V4.000.0000000.0.R.211126.zip
Client	DMSS	Android: 1.99.000
Tool	SmartPlayer	General_SmartPlayer-Win32_Eng_IS_V4.001.0000003.0.R.220225.zip
	Configtool	General_ConfigTool_ChnEng_V5.000.0000001.9.R.20220429.zip
Platform	DSS pro	General_DSS-Professional_Win64_IS_V8.001.0000000.0.R.20220430.exe
	DSS express	General_DSS-Express_win32_IS_V8.000.0000002.0.R.20220429.exe

1.6 Pending Issues

No.	Issue description	Possible result	How to fix
1	With mirroring, enabled, enabling custom BLC will affect the brightness.	When custom BLC is enabled, mirroring or flipping might cause different brightness or color.	You are not recommended to enable regional custom, mirroring, and flipping at the same time.

1.7 Update Guide

For camera upgrade, refer to *WEB3.0_Web Operation Manual*.

ZHEJIANG DAHUA VISION TECHNOLOGY CO., LTD.

Address: No.1199, Bin'an Road, Binjiang District, Hangzhou, P.R. China

Postcode: 310053

Tel: +86-571-87688883

Fax: +86-571-87688815

Email: overseas@dahuatech.com

Website: www.dahuasecurity.com