



RHEA
V2.800.0000008.0.R.190619
Release Notes

ZHEJIANG DAHUA VISION TECHNOLOGY CO., LTD.

Copyright

© 2018 ZHEJIANG DAHUA VISION TECHNOLOGY CO., LTD. All rights reserved.

This document cannot be copied, transferred, distributed, or saved in any form without the prior written permission of Zhejiang Dahua Vision Technology Co., LTD (hereinafter referred to be "Dahua").

The products described in this document may contain the software that belongs to Dahua or the third party. Without the prior written approval of the corresponding party, any person cannot (including but not limited to) copy, distribute, amend, abstract, reverse compile, decode, reverse engineer, rent, transfer, sublicense the software.

Trademarks

 and **HDCVI** are the trademarks or registered trademarks of Dahua.

All other company names and trademarks mentioned herein are the properties of their respective owners.

Disclaimer

- These release notes are for reference only, and the actual product shall prevail.
- Succeeding products and release notes are subject to change without notice.
- If there is any uncertainty or controversy, please refer to our final explanation.



Table of Contents

Legal Information	I
Release Notes	1
1.1 Overview	1
1.2 New Features	1
1.3 Fixed Bugs	1
1.4 Compatibility.....	1
1.4.1 Program	1
1.4.2 Browser.....	2
1.4.3 Third Party Access.....	2
1.5 Software Environment.....	2
1.6 Pending Issues.....	3
1.7 Update Guide.....	1

1.1 Overview

Item	Description
Product model	S3LM platform series
Version	V2.800.0000008. 0.R.190619
Software package information	DH_IPC-HX5X3X-Rhea_MultiLang_NP_Stream3_V2.800.0000008.0.R.190619.zip DH_IPC-HX5X3X-Rhea_MultiLang_PN_Stream3_V2.800.0000008.0.R.190619.zip DH_IPC-HX2X3X-Rhea_MultiLang_NP_Stream3_V2.800.0000008.0.R.190619.zip DH_IPC-HX2X3X-Rhea_MultiLang_PN_Stream3_V2.800.0000008.0.R.190619.zip
OS requirement	None
Release date	2019/6/19

1.2 New Features

Feature	Description

1.3 Fixed Bugs

Fixed bugs	Description
1	Some alarm emails cannot be sent successfully.

1.4 Compatibility

1.4.1 Program

- For IPC-HX2(1)XXX:
2.6.01.05.05757:DH_IPC-HX2X3X-Rhea_MultiLang_PN_Stream2_V2.800.0000000.0.R.181226.zip
2.6.01.05.05759:DH_IPC-HX2X3X-Rhea_MultiLang_NP_Stream2_V2.800.0000000.0.R.181226.zip
2.6.01.05.05761:General_IPC-HX2X3X-Rhea_Eng_NP_Stream2_V2.800.0000000.0.R.181226.zip
2.6.01.05.05763:General_IPC-HX2X3X-Rhea_Eng_PN_Stream2_V2.800.0000000.0.R.181226.zip

1.4.2 Browser

WIN7+IE11、
WIN7+IE9、
WIN7+IE10、
WIN7+chrome70.0.3538.102、
WIN7+Firefox63.0.3、
WIN10+Edge42.17134.1.0

1.4.3 Third Party Access

- CGI testing tool version: V3.01.5
- ONVIF testing tool version: V18.06
- ONVIF: Supports ProfileG
- MILESTONE testing tool version: Xprotect Corporate 2018,device pack 9.6a
- GENETEC testing tool version: Genetec Unit Certification ToolVersion 5.7.607.40

1.5 Software Environment

Platform	Model	Version
NVR	NVR1104-P-S2	General_NVR11XX-S2_Eng_V3.215.0000000.4.R.180513.zip
	NVR2104-P-4KS2	DH_NVR2XXX-4KS2_MultiLang_V3.216.0000000.0.R.180705.zip
	NVR4208-8P-4KS2	DH_NVR4XXX-4KS2_Chn_V3.216.0000000.0.R.180605.zip
	DH-NVR5432-4KS2	DH_NVR5XXX-4KS2_MultiLang_V3.216.0000002.0.R.20181106.zip
	HCVR8816S-S3	DH_HCVR8xxx_Chn_P_V3.218.0000.0.R.20170613.zip
Client	SmartPSS	General_SMARTPSS-Win32_ChnEng_IS_V2.002.0000007.0.R.181023.zip
	DMSS	V4.11.000
	EasyViewer	V3.52.004
	iMOU	V3.9.7.1123
配套 Tool	Player	General_SmartPlayer-Win32_Eng_IS_V4.000.0000000.5.R.20180201.zip
	ConfigTool	General_ConfigTool_ChnEng_V4.011.0000000.0.R.20180906
	PlaySDK	General_PlaySDK_Chn_Windows32_IS_V3.040.0000000.2.R.180704.zip
	NetSDK	General_NetSDK_Chn_Win32_IS_V3.050.0000004.0.R.181121
DSS	DSS7016	V1.000.0000002.0.R.20181101_232222.1035697
	DSSpro	V7.002.0000000.0.R.20180911.995427

1.6 Pending Issues

None

1.7 Update Guide

None

ZHEJIANG DAHUA VISION TECHNOLOGY CO., LTD.

Address: No.1199, Bin'an Road, Binjiang District, Hangzhou, P.R. China

Postcode: 310053

Tel: +86-571-87688883

Fax: +86-571-87688815

Email: overseas@dahuatech.com

Website: www.dahuasecurity.com